

Valspar® Professional Multi-Surface Primer

No. 11299 series

GENERAL DESCRIPTION

Valspar® Professional Multi-Surface primer is formulated to block stains, including heavy tannins. It provides your oil or latex topcoats with optimal adhesion, durability and finish. It resists peeling, blistering and cracking.

PRODUCT FEATURES

- · Great stain and tannin blocking
- Outstanding adhesion to hardwoods and metal
- Improves topcoat adhesion and durability
- Good adhesion to glossy surfaces and clear
 coats
- · Can be applied by spray, brush and roll

RECOMMENDED USES

- Hardwoods
- Cedar
- Redwood
- Non-galvanized metal*
- · Previously painted surfaces

SHIPPING AND PACKAGING

Freight Classification: Paint or paint related material. Protect from freezing.

Packaging:

Gallon – 4 per carton Quart – 4 per carton

COMPOSITION

Base and Fill Levels

(oz./gal.) 128

White

<u>APPLICATION AND CLEANUP</u>

Application: Stir thoroughly. Intermix containers to ensure uniform color. Apply with a premium-quality roller, premium quality synthetic brush or airless sprayer. If applying by spray, back-roll or backbrush to work paint into the surface. Apply a liberal coat of primer uniformly, working well into the surface. Surface conditions and application technique can also impact coverage.

Cleanup: Mineral spirits

Airless Spray:

Pressure: 2000 PSI Tip: 0.017–0.021"

Brush: premium-quality nylon or polyester brush **Roller**: premium quality synthetic, 3/8 – 1/2" nap

SYSTEM RECOMMENDATIONS

Wood:

1 Coat Valspar® Professional Multi-Surface Primer

1-2 Coats Valspar® Paint

Non-galvanized metal:

1 Coat Valspar® Professional Multi-Surface Primer

1-2 Coats Valspar® Paint

Previously Painted Surfaces:

1 Coat Valspar® Professional Multi-Surface Primer

1-2 Coats Valspar® Paint

PRODUCT SPECIFICATIONS

Vehicle Type: Alkyd

Pigment Type: Titanium dioxide Viscosity: 85-95 Krebs Units Sheen: 0–10 Units @ 85° angle

Flashpoint: N/A

VOC: < 350 g/L as per 40 CFR 59.406

Volume Solids: 55% Weight Solids: 77%

Weight Per Gallon: 12.8 lbs./gal

Practical Coverage: Up to 400 sq. ft. per gallon (37 m² per 3.78 L) depending on surface porosity.

Recommended Film Thickness: 4.0 mil Wet 2.2 mil Dry

Dry Time @ 77 °F and 50% Relative Humidity

To Touch: 2-4 hours Recoat: 24 hours

Washing Instructions: Wait at least 7 days before washing with a mild detergent and soft sponge Application Temperature: 50–90 °F (10–32 °C) Storage Temperature: 40–90 °F (5–32 °C)

REGULATORY COMPLIANCE

 Current as of: 12/21/2020

 SCAQMD
 No

 CARB 2000 SCM
 No

 CARB 2007 SCM
 No

 OTC
 Yes

 OTC Phase II
 No

 US National
 Yes

STORAGE AND DISPOSAL

Do not freeze. Keep container closed when not in use. Do not transfer contents to other containers for storage or disposal. In case of spills, absorb with inert material such as sand or kitty litter. Dispose of empty container or unused portion in accordance with local, state and federal regulations.

^{*}Note: Does not contain rust inhibitors



Valspar® Professional Multi-Surface Primer

No. 11299 series

SURFACE PREPARATION

General:

Read the Lead Warning paragraph.

Surfaces must be clean, dry and dull prior to application. Thoroughly clean the surface and allow to dry. Scuff sand glossy surfaces. Remove wallpaper and loose, peeling paint. Scrape and sand peeled or damaged paint. All dust should be removed.

Wood:

Sand wood smooth and patch holes and imperfections with wood filler or putty and sand smooth. Remove all sanding dust.

Plaster:

Allow new plaster to fully cure and sand smooth. Soft and deteriorating plaster can be treated with 1-pint of household vinegar to 1-gallon of water, repeat until surface is hard. Rinse with water and allow to dry prior to priming.

Metal:

Remove all dirt, dust, grease and oils by using a non-residue cleaner to clean the surface. Scrape off any loose, cracked or peeling paint. Any rusted areas or materials susceptible to rust must be treated with a rust-inhibitive primer.

Previously Painted Surfaces:

Remove all dirt, dust, grease and oils by using a non-residue cleaner to clean the surface. Scrape off any loose, cracked or peeling paint. Patch cracks and nail holes. Sand smooth, then prime entire surface or spot prime patches.

Smoke/Fire/Stained surfaces:

Clean the surface thoroughly and allow to dry before applying to smoke or fire damaged areas. Allow to dry for 4 hours after priming and apply your paint in a test area to validate blocking prior to painting your whole area. If the stain bleeds through, apply another coat of primer and allow to dry overnight. Then retest a small area with paint.

LEAD WARNING

WARNING! Removal of old paint by sanding, scraping or other means may generate dust or fumes that contain lead. Exposure to lead dust or fumes may cause brain damage or other adverse health effects, especially in children or pregnant women. Controlling exposure to lead or other hazardous substances requires the use of proper protective equipment, such as a properly fitted respirator (NIOSH approved) and proper containment and cleanup. For more information, call the National Lead Information Center at 1-800-424-LEAD (in US) or contact your local health authority.

WARRANTY

Satisfaction Guaranteed - Limited Warranty

This product is warranted to perform to your satisfaction at the time of application when applied to a properly prepared residential surface in accordance with the label directions and excludes failure due to deterioration of the underlying surface, structural defects or failure of previous product. If the product fails to perform to your satisfaction, return any unused portion to the store with proof-of-purchase and you will receive, as your sole remedy under this warranty, your choice of additional product of equal value or a full refund. THIS WARRANTY EXCLUDES LABOR OR THE COST OF LABOR FOR THE APPLICATION OF ANY PRODUCT AND EXCLUDES ANY INCIDENTAL OR CONSEQUENTIAL DAMAGES. Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitations or exclusions may not apply to you. This warranty gives you specific rights, and you may also have other rights which vary from state to state.

MILDEW

Mildew is a fungus that looks like dirt, but won't wash off. Mildew must be removed before painting or it will grow through any new coat of paint. To remove mildew or suspected mildew, scrub surface before painting with a commercial mildew remover or a solution of 1 part liquid chlorine bleach to 3 parts water. Rinse thoroughly. Avoid contact with skin and eyes. Protect skin and eyes by wearing rubber gloves and eye goggles when working with bleach solution.

CAUTIONS

CONTAINS **ALIPHATIC** HYDROCARBONS. Contents are COMBUSTIBLE. Keep away from heat and open flame. VAPOR HARMFUL. Use only with adequate ventilation. To avoid overexposure, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headaches, or dizziness, increase fresh air, or wear respiratory protection (NIOSH approved) or leave the area. Avoid contact with eyes and skin. Wash hands after using. Keep container closed when not in use. Do not transfer contents to other containers for storage. FIRST AID: In case of eye contact, flush thoroughly with large amounts of water for 15 minutes and get medical attention. For skin contact, wash thoroughly with soap and water. In case of respiratory difficulty, provide fresh air and call physician. If swallowed, call Poison Control Center, hospital emergency room, or physician immediately. DELAYED EFFECTS FROM LONG TERM OVEREXPOSURE. Contains solvents which can cause permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal. WARNING: This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. DO NOT TAKE INTERNALLY, KEEP OUT OF THE REACH OF CHILDREN. DANGER: Rags, steel wool, other waste soaked with this product, and sanding residue may spontaneously catch fire if improperly discarded. Immediately place rags, steel wool, other waste soaked with this product, and sanding residue in a sealed, water-filled, metal container. Dispose of in accordance with local fire regulations.

First Aid: Eye Contact: Immediately flush with plenty of water for at least 15 minutes. If irritation persists, get medical attention.* If Inhaled: If affected by inhalation of vapor or spray mist, move to fresh air. If breathing difficulty continues, get medical attention.* If Swallowed: Drink 2 glasses of water. Get medical attention immediately.*

*Call poison control center, hospital emergency room or physician immediately.

For additional safety and chronic health hazard information, refer to the Material Safety Data Sheet for this product.

EMERGENCY MEDICAL TELEPHONE: 1-888-345-5732

101 W. Prospect Ave. Cleveland, OH 888.313.5569 valsparpaint.com Revised: 12/21/200

Version: 11299A